


USB Driver Installation Guide for Windows 7

Document number:	
Topic:	USB Driver Installation Guide for Windows 7
Date:	06 April 2011
Author:	DD
Version:	V1.0
Referring documents:	-

Step 1: Connect the USB cable to the AccessMini or ETH_IV Device and open the Hardware Manager.


Search conflicting devices in Hardware Manager

Start< Control Panel< Hardware and Sound< Device Manager




If Windows 7 can't recognize a device, because its driver is missing, it marks the device with a yellow warning sign. If the operating system could not place the device in any category, it appears under the 'Unknown Device',

Step 2: Right click on the mouse and choose "driver update"




USB Driver Installation Guide for Windows 7


Step 3: Choose the second point "Browse my computer for drivers"



Step 4: unzip ETH_IV_USB_Driver_Windows7ZIP file.
Be sure that in folder will be the file .sys and .inf. Choose the folder where the driver is stored and install the driver



Step 5: after successful installation a new driver Orion3 USB-Serial will appear in Hardware Manager.



Remember the COM port number. You need use it in your favorite Terminal application software.